Register entry, as of 29 October 2026 Listed for sale Record ID bdd244fa5cdf

2024 Volkswagen Atlas Cross Sport 4Motion SEL

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1V2	BE2CA	1	R	C	222275
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen Group Of Ame…	Atlas Cross Sport · 2.0 L	Verified	2024	Chattanooga	Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Atlas Cross Sport	Drive	AWD
Trim	4Motion SEL	Maker	VOLKSWAGEN GROUP OF AMERICA, INC.
Body	Sport Utility Vehicle	Plant	Chattanooga, Tennessee, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/atlas-cross-sport/2024

7 recalls listed by Transport Canada for this model year

Visual system

2026357 22 Jul 2026

Issue: Under certain conditions, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to update the rearview camera software.

Suspension

2025355 25 Jun 2025

Issue: On certain vehicles, certain bolt(s) on the chassis, brake system and/or suspension may not have been tightened properly. As a result, the bolt(s) could loosen and cause a loss of control. Safety Risk: A loss of control could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the affected bolt(s) on the chassis, brake system and/or suspension.

Visual system

2025272 21 May 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display properly. Canadian regulations require the rearview image to display properly when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display properly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to update the infotainment display software.

Engine
2025079 17 Feb 2025

Issue: On certain vehicles, the engine cover may come loose after service. If this happens, the engine cover could contact hot surfaces in the engine compartment and melt. Safety Risk: An engine cover that melts onto a hot surface could create the risk of a fire. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to remove the engine cover.

Brakes
2024568 27 Sep 2024

Issue: On certain vehicles, the brake master cylinder may not have been manufactured properly. As a result, there could be reduced braking. Note: This problem could cause the brake pedal to feel soft and/or spongy and a brake warning light could turn on in the instrument cluster. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the brake master cylinder.

Visual system
2024365 27 Jun 2024

Issue: On certain vehicles, a software problem could cause the rearview camera image to be delayed or not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to update the infotainment software.

1 more on the model-year record, cardog.app/tools/recalls/volkswagen/atlas-cross-sport/2024

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $40,457[5], $1,423 over the median of $39,034[4].

Lowest ask	$30,811
Middle half	$37,443 – $41,662
Median ask	$39,034
This car	$40,457

Same configuration · 26 live listings · as of 28 Oct 2026

OTHER 2024 VOLKSWAGEN ATLAS CROSS SPORT LISTINGS [5]

Edmonton, AB · 42,880 km	$39,700
St. John's, NL · 57,567 km	$42,995
London, ON · 29,416 km	$39,800
Mississauga, ON · 29,401 km	$39,800
Leamington, ON · 29,401 km	$39,800
Vancouver, BC · 9,869 km	$44,685

§4 EVENTS

2024 **Model year 2024**[1]
Assembly plant Chattanooga, Tennessee, United States

19 Jun 2024	Transport Canada recall 2024354[2] Issued for the model year · Airbag
27 Jun 2024	Transport Canada recall 2024365[2] Issued for the model year · Visual system
27 Sep 2024	Transport Canada recall 2024568[2] Issued for the model year · Brakes
17 Feb 2025	Transport Canada recall 2025079[2] Issued for the model year · Engine
21 May 2025	Transport Canada recall 2025272[2] Issued for the model year · Visual system
25 Jun 2025	Transport Canada recall 2025355[2] Issued for the model year · Suspension
22 Jul 2026	Transport Canada recall 2026357[2] Issued for the model year · Visual system
27 Oct 2026	Listed for sale, Saskatoon, SK[5] Volkswagen Centre Of Saskatoon · asking $40,457
28 Oct 2026	Listing last updated[5] asking $40,457

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 26 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.