Register entry, as of 29 October 2026 Listed for sale Record ID 906f9d9478bb

2015 Chevrolet Impala LT (2LT)

3.6 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2G1	125S3	0	F	9	147901
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Impala · 3.6 L	Verified	2015	Oshawa #1	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	3.6 L, 6 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Impala	Drive	Not in the decode
Trim	LT (2LT)	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Oshawa #1, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/impala/2015

4 recalls listed by Transport Canada for this model year

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Airbag

2015325 22 Jul 2015

Certain vehicles equipped with front vented-heated passenger seats may not comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 208 - Occupant Protection. The Automatic Occupant Sensing (AOS) system may contain a calibration-learning error that will cause the AOS system to fail to suppress the front passenger airbag when an infant seat is placed in the front passenger seat. The front-passenger airbag status light will indicate that the airbag is “on” when the passenger seat is not occupied or is occupied by an infant. Additionally, the front-passenger seat’s safety-belt warning light and chime may turn on when the passenger seat is not occupied and the seatbelt is not buckled. If, despite safety warnings and provincial regulations, a child was placed in a child car seat secured in the passenger front position, the active airbag could deploy in a crash causing potential injury. Correction: Dealers will correct the calibration-learning error by preconditioning the empty seat and resetting the seat zero-value in the ECU.

Brakes

2014380 9 Sep 2014

Certain vehicles fail to comply with the requirements of Canada Motor Vehicle Safety Standard 135 - Brake Systems. The electronic parking brake may not fully release, which could cause the brakes to drag. In this condition, the parking brake indicator also may not illuminate even though the parking brake is engaged, contrary to the requirements of the standard. Brake drag could affect vehicle acceleration and cause undesired deceleration, excessive brake heat, and premature wear to some brake components. If the brake drag is significant or if the vehicle is operated for an extended period of time in this condition, there is a potential for the rear brakes to generate significant heat, smoke and sparks. Correction: Dealers will update the electronic parking brake software.

Other

2014341 11 Aug 2014

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard 201 - Occupant Protection. The center console door may not remain closed in a rear impact, contrary to the requirements of the standard. This could increase the risk of injury in a crash. Correction: Dealers will replace the center console door latch.

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $8,998[5], $3,497 under the median of $12,495[4].

Lowest ask	$8,998
Middle half	$11,246 – $12,995
Median ask	$12,495
This car	$8,998

Same model year · 4 live listings · as of 29 Oct 2026

OTHER 2015 CHEVROLET IMPALA LISTINGS [5]

Haliburton, ON · 145,307 km	$12,995
Oshawa, ON · 147,490 km	$12,995

§4 EVENTS

2015	Model year 2015[1] Assembly plant Oshawa #1, Ontario, Canada
11 Aug 2014	Transport Canada recall 2014341[2] Issued for the model year · Other
9 Sep 2014	Transport Canada recall 2014380[2] Issued for the model year · Brakes
22 Jul 2015	Transport Canada recall 2015325[2] Issued for the model year · Airbag
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other

28 Oct 2026 Listed for sale, Ottawa, ON[5]
MTC AUTO SALES · asking $8,998

§5 DOCUMENTS

Window sticker This VIN reads as model year 1985 or 2015, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 4 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.