

Register entry, as of 28 October 2026

Listed for sale

Record ID 20f6798309bf

2017 Jeep Compass Longitude(BUX), North(Canada), Latitude(Mex, U.S.)

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3C4

WMI 1-3

Jeep · CHRYSLER DE MEXI...

NJDBB

DESCRIPTOR 4-8

Compass · 2.4 L

1

CHECK 9

Verified

H

YEAR 10

2017

T

PLANT 11

Toluca

665156

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	2.4 L, 4 cylinders
Make	Jeep	Fuel	Gasoline
Model	Compass	Drive	4WD
Trim	Longitude(BUX), North(Canada), Latitude(Mex, U.S.)	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Sport Utility Vehicle	Plant	Toluca, State Of Mexico, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/compass/2017

6 recalls listed by Transport Canada for this model year

Label 2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Accessories 2017663 22 Dec 2017

On certain vehicles equipped with the Roadside Emergency Kit containing a Kidde fire extinguishers with black plastic handles and valves, the fire extinguishers may become clogged or require excessive force to activate. Also, the nozzle may detach from the valve assembly with enough force that it could cause injury, and fail to discharge. In case of fire, failure of the extinguisher to function could result in injury and/or property damage. Correction: Dealers will replace the suspect Kidde fire extinguisher with a new Kidde fire extinguisher with a steel nozzle. For more information about recalled fire extinguishers, please visit <https://inmarmarketaction.com/kidde/Kidde284CA/> www.kidde.com

Label 2017585 28 Nov 2017

Certain vehicles fail to comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 205 - Glazing Materials. The rear lift gate glass panel is labeled with the luminous transmittance number "AS2" instead of the correct number "AS3". Correction: No corrective recall action is required as the technical non-compliance condition is deemed to be non-safety related.



Lights and instruments

2017575 22 Nov 2017

Certain vehicles may not comply with Canada Motor Vehicle Safety Standard (CMVSS 101) – Location and Identification of Controls and Displays. The photo-sensor calibration of the instrument cluster panel may not detect day-to-night lighting transition correctly. This could prevent the instrument cluster panel from providing backlighting with at least two levels of brightness contrary to the requirements of the standard. Correction: Dealers will update the instrument cluster panel software with new photo-sensor calibrations as necessary.

Other

2017334 7 Jul 2017

Certain vehicles may have User's Guides containing incorrect information regarding jump start procedures. The battery jumping section in the affected User's Guide depicts the battery terminals with reversed polarity in the battery terminal graphic. If a person were to follow the procedure listed within the User's Guide for jump starting, the risk of a possible electrical hazard injury would be increased due to the incorrect terminal polarity graphic. Correction: Dealers will replace the User's Guide with the a corrected version.

Powertrain

2017251 10 May 2017

On certain vehicles equipped with a 6-speed Aisin transmission, the left front halfshaft may disengage from the transmission and/or break. If this occurs, the vehicle would lose motive power and the park function, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the left front halfshaft for proper engagement in the transmission and replace the left front halfshaft if it is not properly engaged.

Listed for the model year, not checked against your VIN. Jeep confirms which apply.

Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.

www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$16,999^[5], \$3,003 over the median of \$13,996^[4].



Lowest ask	\$8,495
Middle half	\$12,371 – \$15,746
Median ask	\$13,996
This car	\$16,999

Same model year · 24 live listings · as of 28 Oct 2026

OTHER 2017 JEEP COMPASS LISTINGS [5]

Sudbury, ON · 100,975 km	\$14,995
Leduc, AB · 89,250 km	\$19,803
Oshawa, ON · 146,311 km	\$14,970
Regina, SK · 117,370 km	\$14,995
Ottawa, ON · 83,223 km	\$16,598
Edmonton, AB · 135,443 km	\$13,997

§4 EVENTS

2017

Model year 2017^[1]

Assembly plant Toluca, State Of Mexico, Mexico



10 May 2017	Transport Canada recall 2017251 ^[2] Issued for the model year · Powertrain
7 Jul 2017	Transport Canada recall 2017334 ^[2] Issued for the model year · Other
22 Nov 2017	Transport Canada recall 2017575 ^[2] Issued for the model year · Lights and instruments
28 Nov 2017	Transport Canada recall 2017585 ^[2] Issued for the model year · Label
22 Dec 2017	Transport Canada recall 2017663 ^[2] Issued for the model year · Accessories
15 Aug 2024	Transport Canada recall 2024548 ^[2] Issued for the model year · Label
25 Oct 2025	Listed for sale, London, ON ^[5] EcoMotors Auto sales · asking \$16,999
14 Sep 2026	Window sticker collected ^[6] Issued by STELLANTIS
28 Oct 2026	Listing last updated ^[5] asking \$16,999

§5 DOCUMENTS ^[6]

Window sticker	PDF, issued by STELLANTIS, collected 14 Sep 2026 VIN not read from the file
----------------	--

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 24 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | [6] Window sticker, issued by STELLANTIS, collected 14 Sep 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote, live public dealer listings and the window sticker. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

