Register entry, as of 28 October 2026 Listed for sale Record ID 613cb4c023e9

2018 Nissan Micra

1.6 L, 4 cylinders · 4x2 · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3N1	CK3CP	X	J	L	282933
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Nissan Mexicana, S.A. De C...	Micra · 1.6 L	Verified	2018	Aguascalientes	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	1.6 L, 4 cylinders
Make	Nissan	Fuel	Gasoline
Model	Micra	Drive	4x2
Trim	Not in the decode	Maker	NISSAN MEXICANA, S.A. DE C.V.
Body	Hatchback	Plant	Aguascalientes, Aguascalientes, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/micra/2018

2 recalls listed by Transport Canada for this model year

Visual system

2019459 13 Sep 2019

Issue: On certain vehicles, the rear view camera system does not return to the default setting when the transmission is shifted to reverse. This could cause a reduction in rear visibility if a driver had previously adjusted the camera display. Canadian regulations require that the rear view image returns to its original setting each time the camera is turned on. Safety Risk: Reduced rear visibility could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to update the software for the rear view camera.

Electrical

2018440 22 Aug 2018

On certain vehicles equipped with a mechanical key ignition system, a spring in the ignition switch could wear and break. This may allow the ignition key to inadvertently move from the ON position to the accessory (ACC) position while driving, causing the engine to shut off and the airbag system to lose power. The resulting loss of motive power, and change in steering and brake forces could increase the risk of a crash causing injury and/or damage to property. Additionally, in the event of a crash, this may also cause the airbags not to function. Correction: Dealers will inspect the lot number of the ignition switch, and replace it with a new one if it is affected. Note: Until the correction is performed, owners are advised to remove all objects from the ignition key ring, such as additional keys, key chains, etc.

Listed for the model year, not checked against your VIN. Nissan confirms which apply.
Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
www.nissan.ca/service/vin-recall.html

§3 VALUE [3]

This car asks $9,650[4], $1,027 under the median of $10,677[3].



Lowest ask	$6,990
Middle half	$9,574 – $12,524
Median ask	$10,677
This car	$9,650

Same configuration · 15 live listings · as of 28 Oct 2026

OTHER 2018 NISSAN MICRA LISTINGS [4]

La Malbaie, QC · 70,986 km	$11,499
Surrey, BC · 88,565 km	$13,550
Penticton, BC · 40,418 km	$16,904
Kelowna, BC · 40,418 km	$16,904
London, ON · 155,600 km	$9,888
Sherbrooke, QC · 136,850 km	$8,995

§4 EVENTS

2018	Model year 2018[1] Assembly plant Aguascalientes, Aguascalientes, Mexico
22 Aug 2018	Transport Canada recall 2018440[2] Issued for the model year · Electrical
13 Sep 2019	Transport Canada recall 2019459[2] Issued for the model year · Visual system
26 Oct 2026	Listed for sale, Québec, QC[4] belleauauto.com · asking $9,650
27 Oct 2026	Listing last updated[4] asking $9,650

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same configuration, 15 live listings, as of 28 Oct 2026
[4] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.