Register entry, as of 29 October 2026 Listed for sale Record ID eed406866a13

2021 Volkswagen Tiguan S

2.0 L, 4 cylinders · FWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VV	1B7AX	3	M	M	072382
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen De Mexico Sa…	Tiguan · 2.0 L	Verified	2021	Puebla	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Tiguan	Drive	FWD
Trim	S	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Sport Utility Vehicle	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/tiguan/2021

6 recalls listed by Transport Canada for this model year

Visual system

2022382 20 Jul 2022

Issue: Under certain conditions, the rearview camera image may not appear on the center screen. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to update the infotainment software.

Structure

2022170 6 Apr 2022

Issue: This recall is for accessory rear hatch spoilers that were installed on a new vehicle or sold as an accessory part at a Volkswagen dealership. On certain vehicles, the rear spoiler might not be properly attached to the hatch. As a result, the spoiler could detach from the vehicle while driving. Safety Risk: A spoiler that detaches from the vehicle could create a hazard for other drivers and nearby people. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to replace the rear hatch spoiler.

Suspension

2022132 23 Mar 2022

Issue: On certain vehicles, the rear suspension knuckles could crack and/or break. A rear knuckle that breaks while driving could cause a sudden loss of vehicle stability. Safety Risk: A loss of vehicle stability could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to inspect and, if necessary, replace one or both rear suspension knuckles.

Seats and restraints

2021031 27 Jan 2021

Issue: On certain vehicles, the driver's seat frame may not have been properly welded. As a result, the seat frame could fail and move in a crash. Safety Risk: A seat frame that fails could cause an increased risk of injury in a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the driver's seat. The seat frame will be replaced, as necessary.

Brakes

2021014 20 Jan 2021

Issue: On certain vehicles, a front brake hose may be too long and could rub against the steering mechanism. This can cause damage to the hose that could result in a brake fluid leak. If this happens, a driver may have reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front brake hose. It will be replaced, if necessary.

Visual system

2020556 18 Nov 2020

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display or cause it to freeze. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to update the rearview camera software.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $16,999[5], $4,296 under the median of $21,295[4].

Lowest ask	$13,911
Middle half	$19,495 – $23,815
Median ask	$21,295
This car	$16,999

Same model year · 126 live listings · as of 29 Oct 2026

OTHER 2021 VOLKSWAGEN TIGUAN LISTINGS [5]

Alma, QC · 67,916 km	$20,490
Mirabel, QC · 103,302 km	$18,490
Toronto, ON · 0 km	$20,988
Val-David, QC · 110,152 km	$18,997
Terrebonne, QC · 103,302 km	$18,490
Montréal, QC · 99,998 km	$19,990

§4 EVENTS

2021	Model year 2021[1] Assembly plant Puebla, Mexico
18 Nov 2020	Transport Canada recall 2020556[2] Issued for the model year · Visual system
20 Jan 2021	Transport Canada recall 2021014[2] Issued for the model year · Brakes

27 Jan 2021	Transport Canada recall 2021031[2] Issued for the model year · Seats and restraints
23 Mar 2022	Transport Canada recall 2022132[2] Issued for the model year · Suspension
6 Apr 2022	Transport Canada recall 2022170[2] Issued for the model year · Structure
20 Jul 2022	Transport Canada recall 2022382[2] Issued for the model year · Visual system
28 Aug 2026	Listed for sale, London, ON[5] Sport Motors · asking $16,999
29 Oct 2026	Listing last updated[5] asking $16,999

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 126 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.