

Register entry, as of 28 October 2026

Listed for sale

Record ID 825562a0fe6f

2021 Volkswagen Tiguan 4Motion SEL Premium R-Line

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VV **4B7AX** **0** **M** **M** **145592**

WMI 1-3

Volkswagen De Mexico Sa...

DESCRIPTOR 4-8

Tiguan · 2.0 L

CHECK 9

Verified

YEAR 10

2021

PLANT 11

Puebla

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Tiguan	Drive	AWD
Trim	4Motion SEL Premium R-Line	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Sport Utility Vehicle	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/tiguan/2021

6 recalls listed by Transport Canada for this model year

Visual system

2022382 20 Jul 2022

Issue: Under certain conditions, the rearview camera image may not appear on the center screen. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to update the infotainment software.

Structure

2022170 6 Apr 2022

Issue: This recall is for accessory rear hatch spoilers that were installed on a new vehicle or sold as an accessory part at a Volkswagen dealership. On certain vehicles, the rear spoiler might not be properly attached to the hatch. As a result, the spoiler could detach from the vehicle while driving. Safety Risk: A spoiler that detaches from the vehicle could create a hazard for other drivers and nearby people. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to replace the rear hatch spoiler.

Suspension

2022132 23 Mar 2022

Issue: On certain vehicles, the rear suspension knuckles could crack and/or break. A rear knuckle that breaks while driving could cause a sudden loss of vehicle stability. Safety Risk: A loss of vehicle stability could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to inspect and, if necessary, replace one or both rear suspension knuckles.



Seats and restraints

2021031 27 Jan 2021

Issue: On certain vehicles, the driver's seat frame may not have been properly welded. As a result, the seat frame could fail and move in a crash. Safety Risk: A seat frame that fails could cause an increased risk of injury in a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the driver's seat. The seat frame will be replaced, as necessary.

Brakes

2021014 20 Jan 2021

Issue: On certain vehicles, a front brake hose may be too long and could rub against the steering mechanism. This can cause damage to the hose that could result in a brake fluid leak. If this happens, a driver may have reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front brake hose. It will be replaced, if necessary.

Visual system

2020556 18 Nov 2020

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display or cause it to freeze. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to update the rearview camera software.

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.

Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.

www.vw.ca/en/owners-and-drivers/recalls.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$23,985^[5], \$997 over the median of \$22,988^[4].



Lowest ask	\$17,995
Middle half	\$21,825 – \$23,990
Median ask	\$22,988
This car	\$23,985

Same configuration · 40 live listings · as of 28 Oct 2026

OTHER 2021 VOLKSWAGEN TIGUAN LISTINGS [5]

Edmonton, AB · 55,877 km	\$23,997
Burlington, ON · 84,158 km	\$22,798
Burlington, ON · 76,060 km	\$25,998
Steinbach, MB · 125,365 km	\$19,995
Kamloops, BC · 165,119 km	\$14,900
Newmarket, ON · 78,215 km	\$23,988

§4 EVENTS

2021 Model year 2021^[1]
Assembly plant Puebla, Mexico

18 Nov 2020 Transport Canada recall 2020556^[2]
Issued for the model year · Visual system



20 Jan 2021	Transport Canada recall 2021014 ^[2] Issued for the model year · Brakes
27 Jan 2021	Transport Canada recall 2021031 ^[2] Issued for the model year · Seats and restraints
23 Mar 2022	Transport Canada recall 2022132 ^[2] Issued for the model year · Suspension
6 Apr 2022	Transport Canada recall 2022170 ^[2] Issued for the model year · Structure
20 Jul 2022	Transport Canada recall 2022382 ^[2] Issued for the model year · Visual system
26 Oct 2026	Listed for sale, Sainte-Rose - Laval, QC ^[5] Landry Automobiles Dodge Chrysler Jeep Ram · asking \$23,985
27 Oct 2026	Listing last updated ^[5] asking \$23,985

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 40 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

