Register entry, as of 25 November 2026 Listed for sale Record ID 8356036f3c40

2017 Volkswagen Beetle S, Classic, Pink/SE, SEL

1.8 L, 4 cylinders · FWD · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VW	517AT	1	H	M	813373
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen De Mexico Sa…	Beetle · 1.8 L	Verified	2017	Puebla	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	1.8 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Beetle	Drive	FWD
Trim	S, Classic, Pink/SE, SEL	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Convertible	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/beetle/2017

2 recalls listed by Transport Canada for this model year

Airbag

2024649 30 Oct 2024

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the driver-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-front airbag. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

Powertrain

2019423 22 Aug 2019


Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply. Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $16,995[5], $2,446 under the median of $19,441[4].



Lowest ask	$14,943
Middle half	$17,356 – $19,996
Median ask	$19,441
This car	$16,995

Same configuration · 8 live listings · as of 24 Nov 2026

OTHER 2017 VOLKSWAGEN BEETLE LISTINGS [5]

Québec, QC · 78,109 km	$18,995
Calgary, AB · 37,862 km	$24,793
St-Raymond, QC · 117,557 km	$17,477
Woodbridge, ON · 108,345 km	$15,995
Nanaimo, BC · 93,500 km	$16,995
St-Jérôme, QC · 130,001 km	$14,943

§4 EVENTS

2017	Model year 2017[1] Assembly plant Puebla, Mexico
22 Aug 2019	Transport Canada recall 2019423[2] Issued for the model year · Powertrain
30 Oct 2024	Transport Canada recall 2024649[2] Issued for the model year · Airbag
26 Oct 2026	Listed for sale, Midland, ON[5] Midland Honda · asking $16,995
23 Nov 2026	Listing last updated[5] asking $16,995

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 8 live listings, as of 24 Nov 2026

[5] Live public dealer listings on Cardog, as of 25 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.