Register entry, as of 6 November 2026 Listed for sale Record ID 0eb0a936c244

2019 BMW X6 X6 M

4.4 L, 8 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5YM	KW8C5	9	K	0	Y74967
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Bmw Manufacturer Corpor…	X6 · 4.4 L	Verified	2019	United States	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	4.4 L, 8 cylinders
Make	BMW	Fuel	Gasoline
Model	X6	Drive	AWD
Trim	X6 M	Maker	BMW MANUFACTURER CORPORATION / BMW NORTH AMERICA
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/bmw/x6/2019

4 recalls listed by Transport Canada for this model year

Label

2024544 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Structure

2019582 18 Nov 2019

Issue: On certain vehicles, the attachment points for the lower universal anchorage system (for attaching a child seat) could be damaged over time. As a result, a child seat may come loose. Safety Risk: A child seat that is not properly secured could create an increased risk of injury in a crash. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealer to add a reinforcing bracket to the lower anchor bars and the vehicle body.

Suspension

2018538 28 Sep 2018

On certain vehicles, the pivot bolt used on the rear upper control arms could break. If this occurs, it could affect vehicle handling, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace both rear upper control arms.

Wheels

2018496 12 Sep 2018


On certain vehicles, the wheel bolts may not have been properly tightened. This could cause a wheel could become loose and fall off the vehicle, increasing the risk of a crash causing injury and/or damage to property. In addition, the wheel assembly could strike another vehicle, stationary object, or bystander, causing injury and/or property damage. Correction: Dealers will replace the wheel bolts and tighten them to specification.

> Listed for the model year, not checked against your VIN. BMW confirms which apply.
> Check your VIN with BMW Canada or call a BMW dealer with your VIN.
> crm.bmw.ca/en-CA/VehicleRecall

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $63,905[5], $15,963 over the median of $47,942[4].



Lowest ask	$32,999
Middle half	$34,971 – $58,748
Median ask	$47,942
This car	$63,905

Same model year · 6 live listings · as of 5 Nov 2026

OTHER 2019 BMW X6 LISTINGS [5]

Ottawa, ON · 106,715 km	$32,999
Montréal Nord, QC · 91,002 km	$33,999
Edmonton, AB · 97,751 km	$37,888

§4 EVENTS

2019	Model year 2019[1] Assembly plant United States
12 Sep 2018	Transport Canada recall 2018496[2] Issued for the model year · Wheels
28 Sep 2018	Transport Canada recall 2018538[2] Issued for the model year · Suspension
18 Nov 2019	Transport Canada recall 2019582[2] Issued for the model year · Structure
15 Aug 2024	Transport Canada recall 2024544[2] Issued for the model year · Label
1 Nov 2026	Listed for sale, Barrie, ON[5] Georgian BMW · asking $63,905
5 Nov 2026	Listing last updated[5] asking $63,905

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 6 live listings, as of 5 Nov 2026

[5] Live public dealer listings on Cardog, as of 6 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.