

Register entry, as of 28 October 2026

Listed for sale

Record ID 89d6aa388b49

2019 Volvo S60 R-Design

2.0 L, 4 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

7JR A22TM 1 K G 011268

WMI 1-3

Volvo Car Usa, LLC

DESCRIPTOR 4-8

S60 · 2.0 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

South Carolina

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.0 L, 4 cylinders
Make	Volvo	Fuel	Gasoline
Model	S60	Drive	AWD
Trim	R-Design	Maker	VOLVO CAR USA, LLC
Body	Sedan	Plant	South Carolina, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volvo/s60/2019

6 recalls listed by Transport Canada for this model year

Airbag	2023620	21 Nov 2023
Issue: On certain vehicles, the bolts that attach the front-passenger airbag may not have been properly tightened. As a result, the airbag may not inflate properly in a crash. Safety Risk: An airbag that does not work properly could create an increased risk of injury in a crash. Corrective Actions: Volvo will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the front-passenger airbag bolts.		
Visual system	2022595	20 Oct 2022
Issue: On certain vehicles, a software problem could cause the top-view camera to display instead of the rearview camera image when you are reversing. Canadian regulations require the rearview image to display when reversing. Note: This recall only affects vehicles equipped with a 360-degree park assist camera. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners in writing and send a wireless over-the-air update to each vehicle. If the update cannot be completed successfully, or for vehicles without over-the-air (OTA) update capability, Volvo will instruct you to schedule an appointment to have the update performed by a dealer.		
Electrical	2021345	2 Jun 2021
Issue: On certain vehicles, the fuse for the low-pressure fuel pump may be too small. As a result, the fuse could blow and the engine could stall while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Action: Volvo will contact owners by mail and instruct you to take your vehicle to a dealer to replace the 15 A fuse for the low-pressure fuel pump with a 20 A fuse.		



Seats and restraints

2020298 30 Jun 2020

Issue: On certain vehicles, the flexible steel cable that attaches the seat belt to the outside of the front seats may weaken over time. As a result, the seat belt could detach. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Action: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front-outboard seat belt anchors.

Brakes

2020099 13 Mar 2020

Issue: On certain vehicles, the automatic emergency braking system (AEB) may not apply the brakes automatically when it detects a possible collision. In addition, the system may not warn of a potential crash with a non-moving vehicle or object. Note: The regular brake system and all other functions in the vehicle are not affected by this problem. Safety Risk: The AEB system may not provide driver warnings and apply the brakes automatically to help avoid a crash. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to update the vehicle software.

Suspension

2019203 25 Apr 2019

Issue: The locking nuts on the rear suspension toe links may not have been properly tightened during assembly. This could cause a toe link to detach, which would cause a sudden change in vehicle handling. It could also cause the Electronic Stability Control (ESC) system to turn off. Safety Risk: A sudden change in vehicle handling could increase the risk of a crash. Corrective Actions: Volvo will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the rear suspension toe link flange lock nuts. If a nut is found loose, both the bolt and nut will be replaced.

Listed for the model year, not checked against your VIN. Volvo confirms which apply.

Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.

www.volvocars.com/en-ca/l/recall-information/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$24,995^[5], the median^[4].



Lowest ask	\$15,888
Middle half	\$20,770 – \$25,990
Median ask	\$24,995
This car	\$24,995

Same model year · 9 live listings · as of 28 Oct 2026

OTHER 2019 VOLVO S60 LISTINGS [5]

London, ON · 76,264 km	\$25,700
Vaughan, ON · 38,856 km	\$25,898
Toronto, ON · 99,999 km	\$20,770
Burlington, ON · 109,950 km	\$18,888
Etobicoke, ON · 212,409 km	\$15,888
Hamilton, ON · 91,256 km	\$27,995

§4 EVENTS

2019

Model year 2019^[1]

Assembly plant South Carolina, United States



25 Apr 2019	Transport Canada recall 2019203 ^[2] Issued for the model year · Suspension
13 Mar 2020	Transport Canada recall 2020099 ^[2] Issued for the model year · Brakes
30 Jun 2020	Transport Canada recall 2020298 ^[2] Issued for the model year · Seats and restraints
2 Jun 2021	Transport Canada recall 2021345 ^[2] Issued for the model year · Electrical
20 Oct 2022	Transport Canada recall 2022595 ^[2] Issued for the model year · Visual system
21 Nov 2023	Transport Canada recall 2023620 ^[2] Issued for the model year · Airbag
26 Oct 2026	Listed for sale, Québec, QC ^[5] Gosselin Auto · asking \$24,995
28 Oct 2026	Listing last updated ^[5] asking \$24,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 9 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

