Register entry, as of 29 October 2026 Listed for sale Record ID 0b1438c04bb7

2014 Honda Fit LX

1.5 L, 4 cylinders · FWD · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

LUC	GE8H5	8	E	3	001963
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Honda Automobile (China)...	Fit · 1.5 L	Computes	2014	Guangzhou	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	1.5 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	Fit	Drive	FWD
Trim	LX	Maker	HONDA AUTOMOBILE (CHINA) CO., LTD.
Body	Hatchback	Plant	Guangzhou, China

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/fit/2014

5 recalls listed by Transport Canada for this model year

Powertrain

2020610 10 Dec 2020

Issue: On certain vehicles, the paint on the front axle shafts could delaminate or become damaged by road debris. As a result the axle shaft could corrode. If this happens, the axle shafts could break and cause a loss of power to the wheels. Also, if this happens and the vehicle is parked without the parking brake applied, the vehicle could roll away. Safety Risk: A loss of power to the wheels or a vehicle rollaway could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, replace both axle shafts.

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Airbag

2018523 27 Sep 2018

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag inflator.

Airbag

2016046 1 Feb 2016

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will inspect/replace the driver's frontal airbag inflator. Note: Honda Canada has created a special Airbag Inflator Hotline for immediate assistance. For more information, please contact: For Honda Owners: 1-877-445-7754 For Acura Owners: 1-877-445-9844

Powertrain

2014178 20 May 2014

On certain vehicles, the passenger side driveshaft could fracture and separate. If this were to occur while the vehicle is being driven, it could result in a loss of motive power. If this were to occur while the vehicle is parked on an incline without the parking brake applied, it could result in unintended vehicle movement. Both situations could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will replace affected driveshafts.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $9,295[5], $1,300 over the median of $7,995[4].



Lowest ask	$6,957
Middle half	$7,499 – $9,295
Median ask	$7,995
This car	$9,295

Same model year · 5 live listings · as of 29 Oct 2026

OTHER 2014 HONDA FIT LISTINGS [5]

Oshawa, ON · 161,166 km	$9,495
Markham, ON · 200,454 km	$7,995
Toronto, ON · 175,777 km	$7,499
St-Hubert, QC · 207,288 km	$6,957

§4 EVENTS

2014	Model year 2014[1] Assembly plant Guangzhou, China
20 May 2014	Transport Canada recall 2014178[2] Issued for the model year · Powertrain
1 Feb 2016	Transport Canada recall 2016046[2] Issued for the model year · Airbag

27 Sep 2018	Transport Canada recall 2018523[2] Issued for the model year · Airbag
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
10 Dec 2020	Transport Canada recall 2020610[2] Issued for the model year · Powertrain
26 Oct 2026	Listed for sale, Sainte-Rose, QC[5] demirciauto.ca · asking $9,295
29 Oct 2026	Listing last updated[5] asking $9,295

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 5 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.