Register entry, as of 28 October 2026 Listed for sale Record ID 263bce117d05

2018 Volkswagen Golf R Base

2.0 L, 4 cylinders · AWD · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
WVW	VF7AU	4	J	W	298288
Volkswagen Ag	Golf R · 2.0 L	Computes	2018	Wolfsburg	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Golf R	Drive	AWD
Trim	Base	Maker	VOLKSWAGEN AG
Body	Hatchback	Plant	Wolfsburg, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/golf-r/2018

4 recalls listed by Transport Canada for this model year

Fabrics

2021326 26 May 2021

Issue: On certain models, the chrome layer could peel off of the trim located around the gear shift cover. If this happens, sharp edges can be created. Safety Risk: Exposed sharp edges can create the risk of a cut. Corrective Actions: Volkswagen will contact owners by mail and instruct you to take your vehicle to a dealer to replace the gear shift cover trim frame.

Fuel system

2018679 5 Dec 2018

On certain vehicles, an underhood fuel connector may not have been securely attached to the fuel supply line and could result in a fuel leak into the engine compartment. A fuel leak, in the presence of an ignition source, could create the risk of a fire causing injury and/or damage to property. Correction: Dealers will inspect the fuel line connection and ensure it is securely attached.

Structure

2018626 14 Nov 2018

On certain vehicles, the rear seat head restraint guides may not have been properly welded to the seat frame. In a crash, the rear seat head restraints may not remain in place, increasing the risk of injury to vehicle occupants. Correction: Dealers will inspect the rear seat frame, and if the head restraint guide sleeve welds are found to be insufficient, it will be replaced.

Seats and restraints

2018191 18 Apr 2018

Certain vehicles may have been built with defective front seat head rest guide sleeves. This could result in the head rest(s) not locking properly which, in the event of a crash, could cause a head rest to come loose and increase the risk of injury to vehicle occupants. Correction: Dealers will replace the head rest guide sleeves on both front seats.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $26,995[5], $500 over the median of $26,495[4].

Lowest ask	$17,995
Middle half	$22,580 – $28,996
Median ask	$26,495
This car	$26,995

Same configuration · 10 live listings · as of 28 Oct 2026

OTHER 2018 VOLKSWAGEN GOLF R LISTINGS [5]

Kentville, NS · 138,655 km	$22,977
Smiths Falls, ON · 52,249 km	$28,995
Yarmouth, NS · 138,655 km	$22,977
Lacombe, AB · 149,064 km	$28,999
Middleton, NS · 138,655 km	$22,977
Yarmouth, NS · 138,655 km	$22,977

§4 EVENTS

2018	Model year 2018[1] Assembly plant Wolfsburg, Germany
18 Apr 2018	Transport Canada recall 2018191[2] Issued for the model year · Seats and restraints
14 Nov 2018	Transport Canada recall 2018626[2] Issued for the model year · Structure
5 Dec 2018	Transport Canada recall 2018679[2] Issued for the model year · Fuel system
26 May 2021	Transport Canada recall 2021326[2] Issued for the model year · Fabrics
26 Oct 2026	Listed for sale, North Vancouver, BC[5] Jim Pattison Toyota Northshore · asking $26,995
27 Oct 2026	Listing last updated[5] asking $26,995

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 10 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.