Register entry, as of 27 October 2026 Listed for sale Record ID c5b8a42c7788

2012 Volvo S60

2.5 L, 5 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

YV1	622FS	7	C	2	029166
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volvo Car Corporation	S60 · 2.5 L	Computes	2012	Gent Plant	Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	2.5 L, 5 cylinders
Make	Volvo	Fuel	Gasoline
Model	S60	Drive	FWD
Trim	Not in the decode	Maker	VOLVO CAR CORPORATION
Body	Sedan	Plant	Gent Plant, Belgium

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volvo/s60/2012

7 recalls listed by Transport Canada for this model year

Seats and restraints — 2020298 — 30 Jun 2020

Issue: On certain vehicles, the flexible steel cable that attaches the seat belt to the outside of the front seats may weaken over time. As a result, the seat belt could detach. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Action: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front-outboard seat belt anchors.

Lights and instruments — 2013419 — 26 Nov 2013

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard 101 - Controls and Displays. The oil pressure sensor is not activated in the original factory downloaded software. As a result, no oil pressure information would be indicated to the driver in the instrument cluster. Correction: Dealers will update software.

Fuel system — 2012101 — 14 Mar 2012

On certain vehicles, the underbody coating may have been incorrectly formulated and excessively applied during the vehicle assembly process. This can result in rigid, icicle-like formations of underbody coating hanging from the undercarriage of the vehicle, which could damage the fuel lines and cause a leak. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, remove excessive underbody coating near the fuel lines.

Airbag

2012082 28 Feb 2012

On certain vehicles, the wire harness under the driver and/or passenger seat may not have been properly affixed to the seat frame during vehicle assembly. As such, the harness may get caught by the amplifier (mounted under the seat) when seating position is adjusted. If this occurs, the harness connector may detach from the socket and, as a result, the corresponding airbag may not function as intended, causing the instrument panel SRS warning lamp to illuminate. Failure of a frontal airbag to deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will inspect and, if necessary, secure the wire harness to the driver and/or passenger seat frame.

Label

2011388 4 Nov 2011

On certain vehicles equipped with a dealer-installed optional accessory spare tire and wheel kit, the Tire and Loading Information label may not contain correct information. Since the vehicle was originally fitted (by the factory) with a tire inflation kit, the label indicates “none” as the spare tire designation, instead of spare tire size and inflation pressure information. Correction: Dealers will replace the Tire and Loading Information label.

Fuel system

2011218 6 Jun 2011

On certain vehicles, a fuel line quick connector may have been incorrectly manufactured and could fail. Should the connector detach, it could cause engine stalling and a fuel leak. Engine stalling would result in lost propulsion which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash. Fuel leakage, in the presence of an ignition source, could result in a fire. These issues could result in property damage and/or personal injury. Correction: Dealers will replace the high-pressure fuel line assembly.

1 more on the model-year record, cardog.app/tools/recalls/volvo/s60/2012

> Listed for the model year, not checked against your VIN. Volvo confirms which apply.
> Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.
> www.volvocars.com/en-ca/l/recall-information/

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $4,490[5], $2,507 under the median of $6,997[4].



Lowest ask	$4,490
Middle half	$4,991 – $8,874
Median ask	$6,997
This car	$4,490

Same configuration · 8 live listings · as of 26 Oct 2026

OTHER 2012 VOLVO S60 LISTINGS [5]

London, ON · 165,350 km	$7,499
Montreal, QC · 139,546 km	$6,495
Winnipeg, MB · 145,000 km	$11,950
Toronto, ON · 191,332 km	$4,995
Markham, ON · 60,440 km	$10,995
Newmarket, ON · 262,847 km	$4,980

§4 EVENTS

2012	Model year 2012[1] Assembly plant Gent Plant, Belgium
31 May 2011	Transport Canada recall 2011211[2] Issued for the model year · Fuel system
6 Jun 2011	Transport Canada recall 2011218[2] Issued for the model year · Fuel system
4 Nov 2011	Transport Canada recall 2011388[2] Issued for the model year · Label
28 Feb 2012	Transport Canada recall 2012082[2] Issued for the model year · Airbag
14 Mar 2012	Transport Canada recall 2012101[2] Issued for the model year · Fuel system
26 Nov 2013	Transport Canada recall 2013419[2] Issued for the model year · Lights and instruments
30 Jun 2020	Transport Canada recall 2020298[2] Issued for the model year · Seats and restraints
8 Sep 2026	Listed for sale, Brantford, ON[5] Rekona Auto Ltd II · asking $4,490
26 Oct 2026	Listing last updated[5] asking $4,490

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 8 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.