

Register entry, as of 26 October 2026

Listed for sale

Record ID f54e7329aed6

2024 Lamborghini Revuelto

Coupe · Electric

VEHICLE IDENTIFICATION NUMBER [1]

ZHW **CC1ZM** **6** **R** **L** **A00882**

WMI 1-3

Automobili Lamborghini Spa

DESCRIPTOR 4-8

Revuelto

CHECK 9

Computes

YEAR 10

2024

PLANT 11

Bologna

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	Not in the decode
Make	Lamborghini	Fuel	Electric
Model	Revuelto	Drive	Not in the decode
Trim	Not in the decode	Maker	AUTOMOBILI LAMBORGHINI SPA
Body	Coupe	Plant	Bologna, Sant'Agata Bolognese, Italy

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lamborghini/revuelto/2024

3 recalls listed by Transport Canada for this model year

Visual system

2026036 29 Jan 2026

Issue: Under certain conditions, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Lamborghini will notify the owner by mail and advise them to take their vehicle to a dealership to update the rearview camera software.

Structure

2025388 23 Jul 2025

Issue: On a small number of vehicles, the pins securing the gas struts for the doors may not have been tightened properly. As a result, the pin(s) could loosen and detach. If this happens when a door is in the open position, the door could fall and close suddenly. Additionally, this problem could also make it difficult to open the door from inside the vehicle. Safety Risk: A door that falls suddenly could increase the risk of injury. Additionally, a door that is difficult to open could slow your exit from the vehicle in an emergency. This could also increase the risk of injury. Corrective Actions: Lamborghini will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the pins for the doors gas struts.

Visual system

2024626 22 Oct 2024

Issue: On certain vehicles, the connecting rod between the windshield wiper motor and the passenger-side windshield wiper arm could bend and separate. If this happens, the windshield wiper may not work. Safety Risk: Windshield wipers that don't work could reduce visibility and increase the risk of a crash. Corrective Actions: Lamborghini will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the passenger-side wiper connecting rod.



Listed for the model year, not checked against your VIN. Lamborghini confirms which apply.
No online lookup from Lamborghini · call a Lamborghini dealer with your VIN.

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$889,900^[5], \$50,000 over the median of \$839,900^[4].



Lowest ask	\$779,999
Middle half	\$809,950 – \$864,900
Median ask	\$839,900
This car	\$889,900

Same model year · 3 live listings · as of 26 Oct 2026

§4 EVENTS

2024	Model year 2024 ^[1] Assembly plant Bologna, Sant'Agata Bolognese, Italy
22 Oct 2024	Transport Canada recall 2024626 ^[2] Issued for the model year · Visual system
23 Jul 2025	Transport Canada recall 2025388 ^[2] Issued for the model year · Structure
29 Jan 2026	Transport Canada recall 2026036 ^[2] Issued for the model year · Visual system
25 Oct 2026	Listed for sale, Kirkland, QC ^[5] John Scotti Lamborghini Montreal · asking \$889,900
26 Oct 2026	Listing last updated ^[5] asking \$889,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 3 live listings, as of 26 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 26 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

